

# FEDERAL UNIVERSITY OF CEARÁ CENTER OF TECHNOLOGY DEPARTMENT OF STRUCTURAL ENGINEERING AND CIVIL CONSTRUCTION POST-GRADUATION PROGRAM IN STRUCTURES AND CIVIL CONSTRUCTION

ISRAEL NILTON LOPES SOUSA

OPTICAL SENSOR SYSTEM FOR CORROSION MONITORING

## ISRAEL NILTON LOPES SOUSA

## OPTICAL SENSOR SYSTEM FOR CORROSION MONITORING

A Dissertation presented for the Graduate Program in Civil Engineering: Structures and Civil Construction of the Federal University of Ceará, as a fulfillment of the requirements for the Degree of Master. Area within the Graduate Program: Civil Construction.

Advisor: Prof. Esequiel Fernandes Teixeira Mesquita, Ph.D.

Co-advisior: Prof. Antônio Eduardo Bezerra Cabral, Ph.D.

Dados Internacionais de Catalogação na Publicação
Universidade Federal do Ceará
Sistema de Bibliotecas
Gerada automaticamente pelo módulo Catalog, mediante os dados fornecidos pelo(a) autor(a)

S6960 Sousa, Israel Nilton Lopes.

Optical Sensor System for Corrosion Monitoring / Israel Nilton Lopes Sousa. – 2023. 90 f. : il. color.

Dissertação (mestrado) — Universidade Federal do Ceará, Centro de Tecnologia, Programa de Pós-Graduação em Engenharia Civil: Estruturas e Construção Civil, Fortaleza, 2023.

Orientação: Prof. Dr. Esequiel Fernandes Teixeira Mesquita. Coorientação: Prof. Dr. Antônio Eduardo Bezerra Cabral.

1. Fiber Bragg gratings. 2. Optical fiber sensor. 3. Optical fiber accelerometer. 4. Corrosion. 5. Buried pipelines. I. Título.

CDD 624.1

# ISRAEL NILTON LOPES SOUSA

# OPTICAL SENSOR SYSTEM FOR CORROSION MONITORING

A Dissertation presented for the Graduate Program in Civil Engineering: Structures and Civil Construction of the Federal University of Ceará, as a fulfillment of the requirements for the Degree of Master. Area within the Graduate Program: Civil Construction.

Approved in: _	/
	COMMITTEE MEMBERS
	Prof. Esequiel Fernandes Teixeira Mesquita, Ph.D. (Advisor) Federal University of Ceará
	Prof. Antônio Eduardo Bezerra Cabral, Ph.D. (Co-advisor) Federal University of Ceará
	Prof. Camilo Arturo Rodriguez Diaz, Ph.D. Federal University of Espirito Santo
	Prof. Paulo Fernando da Costa Antunes, Ph.D.

University of Aveiro

To my parents José Iranilton and Socorro, my sisters Nara and Izabel for all their love and support during all of these years.

## **ACKNOWLEDGEMENTS**

To my family, for their all support and acceptance throughout the conclusion of the work and throughout my life.

To Prof. Dr. Esequiel Fernandes Teixeira Mesquita, for his guidance and friendship, which were essential for this work.

To Prof. Dr. Antônio Eduardo Bezerra Cabral, for his co-orientation and friendship.

To the University of Aveiro, for the help in the experimental stage, which made this work possible.

To the Laboratory of Rehabilitation and Durability of Constructions (LAREB), and to the laboratory colleagues, who helped with friendship and companionship in carrying out many works.

To FUNCAP and CEGÁS, for the financial support with the funding of the research.

To FAPES, for the financial support with the project no. 2021-45D4X.


To the Corrosion Research Laboratory (LPC), mainly to Prof. Dr. Walney Silva Araújo and to Vitória Lima de Souza, for their valuable contributions and suggestions.

To Prof. Dr. Paulo Fernando da Costa Antunes, Prof. Dr. Nélia Jordão Alberto, and Luis Miguel Antunes Pereira, from the University of Aveiro, for having collaborated in the realization of this work.

To the professors participating in the examining committee Prof. Dr. Camilo Arturo Rodriguez Diaz and Prof. Dr. Paulo Fernando da Costa Antunes for their time and valuable collaborations.

To my friends, for their help and commitment.

Finally, I would like to thank everyone who contributed directly and indirectly to my professional training and personal development.



## **ABSTRACT**

Corrosion is one of the main degradation phenomena to act on metallic structures, resulting in great economic losses. As a result, different techniques to evaluate and monitor this parameter have become the object of study in recent years. There is a great tendency towards the use of optical fiber sensors for monitoring different parameters, thanks to their advantages over traditional electronic sensors, for example, possible use in aggressive and/or explosive environments, immunity to electromagnetic fields, electrical isolation, low weight and size, longer useful life, among others. Optical accelerometers have also gained prominence, integrating the characteristics of optical sensors, and allowing a greater possibility of applications. The application of these sensors is already widespread for monitoring temperature, stress, strain, refractive index, acceleration, and relative humidity, among others. However, despite the wide possibilities of use in engineering structures, there is still a need for further studies on its application in other areas, such as monitoring corrosion in metallic structures, in particular, in pipelines for the transport of flammables. The variation of the natural frequency of a material is related to the variation of its thickness and stiffness, parameters related to corrosion. This relationship establishes the principle governing the measurements of this work. In this way, it is proposed in this dissertation the development and implementation of an optical sensor based on Bragg gratings for continuous monitoring of the loss of thickness in metallic elements subjected to controlled corrosion, in a generalized and uniform way in a carbon steel plate 1020, as well as the development of an optical fiber accelerometer based on Bragg gratings together with pairs of optical fibers based on the same principle for monitoring the corrosion of a pipeline section of the same material, buried and subjected to controlled corrosion, through monitoring the variation of its natural frequency. The results obtained were promising and indicated the detection of corrosion through fiber Bragg gratings on the metallic plate, with a coefficient of determination superior to 67% to all nine sensors, however, in the monitoring of the pipe section, only the optical fiber accelerometer was able to identify corrosion properly by identifying the variation of the natural frequency, with a coefficient of determination equivalent to 74.43% throughout the monitoring.

**Keywords:** Fiber Bragg gratings, Optical fiber sensor, Optical fiber accelerometer, Corrosion, Buried pipelines.

## **RESUMO**

A corrosão é um dos principais fenômenos de degradação a atuar sobre estruturas metálicas, resultando em grandes perdas econômicas. Dessa forma, diferentes técnicas para avaliar e monitorar esse parâmetro tornaram-se objeto de estudo nos últimos anos. Observa-se uma grande tendência à utilização de sensores de fibra óptica para monitoramento de diferentes parâmetros, graças as suas vantagens sobre os sensores eletrônicos tradicionais, como por exemplo, possível utilização em ambientes agressivos e/ou explosivos, imunidade a campos eletromagnéticos, isolamento elétrico, baixo peso e tamanho, maior vida útil, entre outras. Os acelerômetros óticos também tem sido objeto de estudo, integrando as características dos sensores ópticos permitindo uma maior possibilidade de aplicações. A aplicação desses sensores já se apresenta largamente difundidas para o monitoramento de temperatura, tensão, deformação, índice de refração, aceleração, umidade relativa, dentre outros. Apesar das amplas possibilidades de utilização em estruturas de engenharia, ainda se destaca a necessidade de uma ampliação de estudos acerca da sua aplicação em outras áreas como no monitoramento da corrosão em estruturas metálicas, em especial, nos dutos de transporte de inflamáveis. A variação da frequência natural de um material está relacionada a variação de sua espessura e rigidez, parâmetros relacionados à corrosão. Essa relação estabelece o princípio governa as medições deste trabalho. Desta forma, propõe-se nesta dissertação, o desenvolvimento e implementação de sensores óticos com base em redes de Bragg para monitoramento contínuo da perda de espessura em elementos metálicos submetidos a corrosão controlada, de forma generalizada e uniforme em uma placa de aço carbono 1020, assim como o desenvolvimento de um acelerômetro óptico com base em redes de Bragg junto a pares de fibras óticas com base no mesmo princípio para o monitoramento da corrosão de uma seção de duto de mesmo material, enterrada e submetida a uma corrosão controlada, através do monitoramento da variação da sua frequência natural. Os resultados obtidos foram promissores e indicaram a detecção da corrosão através das fibras ópticas com base em redes de Bragg na placa metálica, com coeficiente de determinação superior a 67% para todos os nove sensores, no entanto, no monitoramento da seção do duto, apenas o acelerômetro ótico foi capaz de identificar a corrosão adequadamente, através da variação da frequência natural, com coeficiente de determinação de 74.43% ao longo do monitoramento.

**Palavras-chave:** Redes de Bragg, Sensor de fibra óptica, Acelerômetro óptico, Corrosão, Dutos enterrados.

# LIST OF FIGURES

Figure 1. Structure of the master's thesis.
Figure 2. Causes of pipeline incidents from 1990 to 2010.
Figure 3. Working principle of a fiber Bragg grating
Figure 4. Representation of distributed sensing technologies
Figure 5. (a) FBG sensors position and identification and location of the corrosion site on the metal plate; (b) photograph of the experimental apparatus
Figure 6. Experimental setup of the electrochemical cell
Figure 7. Thickness variation of the metal plate as a function of the corrosion time37
Figure 8. Variation of the calculated lost mass with time using Equation (7) (red line) and the obtained values from Table 1 (black squares)
Figure 9. (a) Sensor 1 response to the application of five vertical impacts, 48 h after applying the 0.1 M NaCl solution; (b) corresponding frequency spectrum after FFT processing40
Figure 10. Natural frequency variation as a function of time of the corrosion process on the metal plate for the nine FBG-based sensors
Figure 11. NaCl solution containing the steel plate corrosion products at different times42
Figure 12. Variation of the calculated lost mass with the corrosion action time using Equation (8) (red line) and the obtained values from Table 3 (black squares)43
Figure 13. Relation between the calculated lost mass and the natural frequency of the plate obtained by each FBG sensor during the entire experiment. Inset images: Natural frequency variation as a function of the calculated lost mass for each FBG sensor during the entire experiment. Inset images: Natural frequency variation as a function of the calculated lost mass for each FBG sensor during the initial 120 h
Figure 14. OCP curves for samples 1, 2, and 3 of 1020 carbon steel in NaCl solution45
Figure 15. Nyquist diagrams for the three samples of 1020 carbon steel immersed in NaCl46
Figure 16. Reflection spectrum of the FBG array, which was fix in the non-coating areas of the pipeline section, with the spectral position and the identification of the sensors54
Figure 17. (a) Blueprint of the proposed mountable/dismountable optical fiber accelerometer (dimensions in mm); (b) Design of the inertial mass; (c) Design of the accelerometer support.
Figure 18. Simulation in the SolidWorks of the inertial mass displacement when subjected to gravity (cantilever dimensions: 15 mm x 20 mm x 2 mm): (a) In the x-axis; (b) In the y-axis;

Simulation in the SolidWorks of the OFA (cantilever dimensions: 20 mm x 20 mm x 0.8 mm): (c) Mesh model; (d) Corresponding $f_{n\_OFA}$
Figure 19. Accelerometer prototype (cantilever dimensions: 20 mm x 20 mm x 0.8 mm) during the characterization tests with one FBG attached
Figure 20. (a) Scheme of the OFA. (b) Reflection spectrum of the FBGs after attaching them to the accelerometer
Figure 21. Scheme of the setup to interrogate the FBGs from the OFA, using a USFBG as edge filter: (a) for static measurement; (b) for dynamic measurement60
Figure 22. (a) Reflection spectra of the accelerometer's FBGs, USFBG and resulting signal; (b) Reflection spectra of the resulting signal for acceleration values of -1 g, 0 g and 1 g; (c) Wavelength variations of FBG 1 and FBG 2, and from their combined response, with the acceleration; (d) Optical power variations of FBG 1 and FBG 2, and from their combined response, with the acceleration
Figure 23. Natural frequency response of the OFA by: (a) optical power variation monitoring; (b) wavelength variation monitoring (inset: obtained data from the induced vibrations, for both cases).
Figure 24. a) Pipeline with the attached FBG sensors; b) Representation of the sensors utilized in the pipeline, as well their specific position
Figure 25. (a) Side view of OFA fixed to the pipeline section; (b) Side view of the sensors positioned in the pipeline and monitoring system; (c) The same pipeline section inside the wood box buried in sand to simulate underground pipelines
Figure 26. Response of the FBG sensors C3, C5, NC4 and NC5 when the pipeline setup was: (a) fixed to the optical table and (b) inside the wood box covered with sand; (c) Response of the OFA and the corresponding frequency when the pipeline setup (without the PVC container attached) was fixed to the optical table (left) and inside the wood box covered with sand (right)
Figure 27. (a) Frequency of the buried pipeline during the corrosion process (164 days), detected by the OFA; (b) Respective natural frequency behavior with normalized amplitude for days 0, 18 and 164.
Figure 28. Correlation between $f_{n_{\text{pipeline}}}$ and time, during the entire corrosion experiment 70
Figure 29. (a) Corrosion site after 164 days since the beginning of the corrosion process; (b) Mass of the material from the corrosion process after 164 days since the beginning of the corrosion process; (c) Variation of the mass of the material from the corrosion process during the experiment
Figure 30. Natural frequency spectra of the pipeline setup with normalized amplitude for situations 2 and 3, before and after the corrosion process, respectively

# LIST OF TABLES

Table 1. Determination of calculated lost mass through ultrasound measurements38
Table 2. Results observed in the correlation between frequency and time41
Table 3. Determination of the q factor, the ratio between the calculated lost mass and the area of the application region of the corrosive solution
Table 4. Results observed in the correlation between frequency and calculated lost mass45
Table 5. Simulated and experimental results regarding the $S_A$ and $f_{n\_OFA}$ of the accelerometer for different cantilever dimensions.
Table 6. f <sub>n_pipeline</sub> at different periods, before and after the corrosion process72

# TABLE OF CONTENTS

1	INTRODUCTION	14
1.1	Motivation	15
1.2	Objectives	17
1.2.1	Main aim	17
1.2.2	Specific objectives	17
1.3	Work organization	17
1.4	Main Contributions	18
2	OPTICAL FIBER SENSORS TECHNIQUES FOR CORROSION	
MONIT	TORING AND EVALUATION IN PIPELINES	19
2.1	Introduction	19
2.1.1	Principle of Corrosion in Metallic Elements	19
2.1.2	Impact of corrosion	20
2.1.3	Techniques for corrosion monitoring	22
2.2	Optical fiber sensors	23
2.2.1	Pointing fiber sensing	24
2.2.1.1	Fiber Bragg grating sensors	24
2.2.1.2	Long-period grating sensors	25
2.2.1.3	Fabry-Perot cavity sensors	26
2.2.2	Distributed sensing technology	27
2.2.2.1	Optical time domain reflectometer	28
2.2.2.2	Optical frequency domain reflectometer	28
2.3	Final comments	28
3	SENSING SYSTEM BASED ON FBG FOR CORROSION MONITOR	RING IN
META	LLIC STRUCTURES	30
3.1	Introduction	30
3.2	Theory of Fiber Bragg Gratings	32
3.3	Experimental procedures	34
3.3.1	Ultrasound Measures	34
3.3.2	FBG-Based Sensing	34
3.3.3	Electrochemical Tests	36
3.4	Results and Discussion	37
3.4.1	Ultrasound Measures	37

3.4.2	FBG-Based Sensing	39
3.4.3	Eletrochemical Tests	45
3.5	Final comments	47
4 FREQ	FBG-BASED ACCELEROMETER FOR BURIED PIPELINE NATURE OF THE PROPERTY OF THE PROP	
4.1	Introduction	49
4.2	Fiber Bragg Gratings	53
4.3	Design and Production of the Optical Fiber Accelerometer	54
4.3.1	Design	54
4.3.2	Simulations	55
4.3.3	Production and Initial Characterization	57
4.3.4	Interrogation system	59
4.4	Natural Frequency Monitoring	63
4.4.1	Principle of operation	63
4.4.2	Experimental procedure	64
4.5	Results and discussion	66
4.6	Final comments	73
5	CONCLUSIONS	75
REFE	RENCES	77
SCIEN	NTIFIC PUBLICATIONS RESULTED FROM THE WORK DEVELO	OPED89

## REFERENCES

ABDEEN, D. H. et al. A review on the corrosion behaviour of nanocoatings on metallic substrates. **Materials**, v. 12, n. 2, 10 jan. 2019.

AHMAD, R.; BANERJEE, S.; KUNDU, T. Pipe wall damage detection in buried pipes using guided waves. **Journal of Pressure Vessel Technology, Transactions of the ASME**, v. 131, n. 1, fev. 2009.

AL HANDAWI, K. et al. Strain based FBG sensor for real-time corrosion rate monitoring in pre-stressed structures. **Sensors and Actuators, B: Chemical**, v. 236, p. 276–285, 29 nov. 2016.

ALBERTA ENERGY REGULATOR. Report 2013-B: Pipeline Performance in Albarta, 1990 - 2012. [s.l: s.n.].

ALHANDAWI, K. B. et al. Corrosion monitoring along infrastructures using distributed fiber optic sensing. Sensors and Smart Structures Technologies for Civil, Mechanical, and Aerospace Systems 2016. Anais...SPIE, 20 abr. 2016.

ALLIL, R. C. DA S. B. Sensores a fibra óptica com tecnologia FBG para medida de temperatura e alta tensão. [s.l.] Universidade Federal do Rio de Janeiro, 2010.

AL-MOUBARAKI, A. H.; OBOT, I. B. Top of the line corrosion: causes, mechanisms, and mitigation using corrosion inhibitors. **Arabian Journal of Chemistry.** Elsevier B.V., 1 maio 2021.

ALMUBAIED, O. et al. Monitoring Corrosion Process of Reinforced Concrete Structure Using FBG Strain Sensor. **IEEE Transactions on Instrumentation and Measurement**, v. 66, n. 8, p. 8, 2017a.

ANTUNES, P. et al. Structural health monitoring of different geometry structures with optical fiber sensors. **Photonic Sensors**, v. 2, n. 4, p. 357–365, 2012a.

ANTUNES, P. et al. Optical fiber sensors for static and dynamic health monitoring of civil engineering infrastructures: Abode wall case study. **Measurement: Journal of the International Measurement Confederation**, 2012b.

ANTUNES, P. F. Sensores ópticos para monitorização dinâmica de estruturas. Aveiro: Universidade de Aveiro, 2011.

ANTUNES, P. F. C. et al. Biaxial optical accelerometer and high-angle inclinometer with temperature and cross-axis insensitivity. **IEEE Sensors Journal**, v. 12, n. 7, p. 2399–2406, 2012c.

ANTUNES, P.; VARUM, H.; ANDRÉ, P. Uniaxial fiber Bragg grating accelerometer system with temperature and cross axis insensitivity. **Measurement: Journal of the International Measurement Confederation**, v. 44, n. 1, p. 55–59, jan. 2011.

- ASSIS, W. S. DE. Sistemas computacionais de apoio à monitoração de estruturas de Engenharia Civil. [s.l.] Universidade de São Paulo, 2007.
- BABAEE, M.; CASTEL, A. Chloride diffusivity, chloride threshold, and corrosion initiation in reinforced alkali-activated mortars: Role of calcium, alkali, and silicate content. **Cement and Concrete Research**, v. 111, p. 56–71, 1 set. 2018.
- BERROCAL, C. G.; FERNANDEZ, I.; REMPLING, R. Crack monitoring in reinforced concrete beams by distributed optical fiber sensors. **Structure and Infrastructure Engineering**, v. 17, n. 1, p. 124–139, 2021.
- BIEZMA, M. V. et al. Most fatal oil & gas pipeline accidents through history: A lessons learned approach. **Engineering Failure Analysis**, v. 110, 1 mar. 2020.
- BUBBICO, R. A statistical analysis of causes and consequences of the release of hazardous materials from pipelines. The influence of layout. **Journal of Loss Prevention in the Process Industries**, v. 56, p. 458–466, 1 nov. 2018.
- BUTUSOVA, Y. N.; MISHAKIN, V. V.; KACHANOV, M. On monitoring the incubation stage of stress corrosion cracking in steel by the eddy current method. **International Journal of Engineering Science**, v. 148, 1 mar. 2020.
- CALABRESE, L.; PROVERBIO, E. A Review on the Applications of Acoustic Emission Technique in the Study of Stress Corrosion Cracking. **Corrosion and Materials Degradation**, v. 2, n. 1, p. 1–33, 23 dez. 2020.
- CHEN, Y. et al. Mechanism and sensitivity of Fe-C coated long period fiber grating sensors for steel corrosion monitoring of RC structures. **Corrosion Science**, v. 127, p. 70–81, 1 out. 2017.
- CHILAMKURI, K.; KONE, V. Monitoring of varadhi road bridge using accelerometer sensor. Materials Today: Proceedings. Anais...Elsevier Ltd, 1 jan. 2020.
- CORREIA, M. J. Sensor for oxygen evaluation in concrete. **Cement e concrete composites**, v. 28, p. 226–232, 2006.
- CUI, P. et al. Measurement of aircraft wing deformation using fiber bragg gratings. **ICOCN 2017 16th International Conference on Optical Communications and Networks**, v. 2017-Janua, n. 1, p. 1–3, 2017.
- DÍAZ, C. A. R. et al. Low-cost interrogation technique for dynamic measurements with FBG-based devices. **Sensors (Switzerland)**, v. 17, n. 10, 23 out. 2017.
- DILER, E. et al. Real-time corrosion monitoring of aluminium alloys under chloride-contaminated atmospheric conditions. **Materials and Corrosion**, v. 72, n. 8, p. 1377–1387, 1 ago. 2021.

DOSHVARPASSAND, S.; WU, C.; WANG, X. An overview of corrosion defect characterization using active infrared thermography. Infrared Physics and TechnologyElsevier B.V., , 1 jan. 2019.

DURRANI, F. et al. Predicting Corrosion rate in Chilled HVAC Pipe Network: Coupon vs Linear Polarisation Resistance method. **Engineering Failure Analysis**, v. 109, 1 jan. 2020.

EDALATI, K. Ã. et al. The use of radiography for thickness measurement and corrosion monitoring in pipes. **Pressure Vessels and Piping**, v. 83, p. 736–741, 2006.

ELIZALDE, J. S. G.; CHIOU, Y. S. Improving the detectability and confirmation of hidden surface corrosion on metal sheets using active infrared thermography. **Journal of Building Engineering**, v. 66, 1 maio 2023.

EWERT, U. et al. Corrosion monitoring with tangential radiography and limited view computed tomography. AIP Conference Proceedings. Anais...American Institute of Physics Inc., 10 fev. 2016.

FAN, L. et al. Magnet-assisted hybrid EFPI/FBG sensor for internal corrosion monitoring of steel pipelines. **Optical Fiber Technology**, v. 73, 1 out. 2022.

FAN, L.; BAO, Y. Review of fiber optic sensors for corrosion monitoring in reinforced concrete. **Cement and Concrete Composites**, v. 120, n. May 2020, p. 19, 2021.

FAYOMI, O. S. I.; AKANDE, I. G.; ODIGIE, S. **Economic Impact of Corrosion in Oil Sectors and Prevention: An Overview**. Journal of Physics: Conference Series. **Anais**...Institute of Physics Publishing, 18 dez. 2019.

FONTANA, M. G. Corrosion Engineering. Singapore: McGraw-Hill Book Co, 1987.

FRINGS, J.; WALK, T. Distributed Fiber Optic Sensing Enhances Pipeline Safety and Security. **OIL GAS European Magazine**, p. 132–136, 2011.

GAO, L. et al. Model Test Study on Oil Leakage and Underground Pipelines Using Ground Penetrating Radar. **Russian Journal of Nondestructive Testing**, v. 56, n. 5, p. 435–444, 1 maio 2020.

GENTIL, V. Corrosão. 3º ed. Rio de Janeiro: [s.n.]. v. 1

GUO, C. et al. Ultrasensitive LPFG corrosion sensor with Fe-C coating electroplated on a Gr/AgNW film. **Sensors and Actuators, B: Chemical**, v. 283, p. 334–342, 15 mar. 2019a.

GUO, S. et al. A critical review of corrosion development and rust removal techniques on the structural/environmental performance of corroded steel bridges. **Journal of Cleaner Production**, v. 233, p. 126–146, 1 out. 2019b.

HASSAN, M. R. A. et al. Optical-based sensors for monitoring corrosion of reinforcement rebar via an etched Cladding Bragg grating. **Sensors (Switzerland)**, v. 12, n. 11, p. 7, 2012.

HE, Y. et al. Steel corrosion characterization using pulsed eddy current systems. **IEEE Sensors Journal**, v. 12, n. 6, p. 2113–2120, 2012.

HILBERT, L. R. Monitoring corrosion rates and localised corrosion in low conductivity water. **Corrosion science**, v. 48, p. 3907–3923, 2006.

HONG, C. et al. A simple FBG pressure sensor fabricated using fused deposition modelling process. **Sensors and Actuators, A: Physical**, v. 285, p. 269–274, 1 jan. 2019.

HONG, L. et al. A multi-cantilever beam low-frequency FBG acceleration sensor. **Scientific Reports**, v. 11, n. 1, p. 1–11, 2021.

HREN, M.; KOSEC, T.; LEGAT, A. Characterization of stainless steel corrosion processes in mortar using various monitoring techniques. **Construction and Building Materials**, v. 221, p. 604–613, 10 out. 2019.

HROMADKA, J. et al. Simultaneous in situ temperature and relative humidity monitoring in mechanical ventilators using an array of functionalised optical fibre long period grating sensors. **Sensors and Actuators, B: Chemical**, v. 286, p. 306–314, 1 maio 2019.

HU, W. et al. Fe-C-coated fibre Bragg grating sensor for steel corrosion monitoring. **Corrosion Science**, v. 53, n. 5, p. 1933–1938, maio 2011.

HUANG, C. Y. et al. A fiber bragg grating-based anemometer†. **Sensors** (**Switzerland**), v. 18, n. 7, 2018.

HUANG, Y. et al. Steel bar corrosion monitoring with long-period fiber grating sensors coated with nano iron/silica particles and polyurethane. **Structural Health Monitoring**, v. 14, n. 2, p. 178–189, 26 mar. 2015.

HUANG, Y.; LIANG, X.; AZARMI, F. **Innovative Fiber Optic Sensors for Pipeline Corrosion Monitoring**. Pipelines 2014: From underground to the Forefront of Innovation and Sustainability. **Anais**...2014.

JAFARZADEH, S.; CHEN, Z.; BOBARU, F. Computational modeling of pitting corrosion. Corrosion ReviewsDe Gruyter, , 2019.

JIANG, S. et al. A high-sensitivity FBG accelerometer and application for flow monitoring in oil wells. **Optical Fiber Technology**, v. 74, 1 dez. 2022.

JIANG, T. et al. Pipeline internal corrosion monitoring based on distributed strain measurement technique. **Structural Control and Health Monitoring**, v. 24, n. 11, 1 nov. 2017.

- JIN, X. et al. High strain sensitivity temperature sensor based on a secondary modulated tapered long period fiber grating. **IEEE Photonics Journal**, v. 11, n. 1, 1 fev. 2019.
- KARIM, F. et al. Measurement of aluminum oxide film by Fabry–Pérot interferometry and scanning electron microscopy. **Journal of Saudi Chemical Society**, v. 21, n. 8, p. 938–942, 1 dez. 2017.
- KIM, H. K.; SHIN, W.; AHN, T. J. UV sensor based on photomechanically functional polymer-coated FBG. **IEEE Photonics Technology Letters**, v. 22, n. 19, p. 1404–1406, 2010.
- KIM, J. T. et al. **Flow-accelerated corrosion monitoring through advanced sensors**. Advanced Sensor Systems and Applications II. **Anais**...SPIE, 14 fev. 2005.
- KOCH, G. et al. International measures of prevention, application, and economics of corrosion technologies study. [s.l: s.n.].
- KOKHANOVSKIY, A. et al. Highly dense fbg temperature sensor assisted with deep learning algorithms. **Sensors**, v. 21, n. 18, 1 set. 2021.
- KORENKO, B. et al. Novel Fiber-Optic Relative Humidity Sensor with Thermal Compensation. **IEEE Sensors Journal**, v. 15, n. 10, p. 5450–5454, 2015.
- KUMAR, S.; BEDI, A.; KOTHARI, V. Design and analysis of FBG based sensor for detection of damage in oil and gas pipelines for safety of marine life. SPIE-Intl Soc Optical Eng, 13 fev. 2018.
- LE, H.-D. et al. A novel short fiber Bragg grating accelerometer based on a V-type dual mass block structure for low- and medium-frequency vibration measurements. **Optics & Laser Technology**, v. 161, p. 109131, jun. 2023.
- LEE, J. R.; YUN, C. Y.; YOON, D. J. A structural corrosion-monitoring sensor based on a pair of prestrained fiber Bragg gratings. **Measurement Science and Technology**, 2010.
- LEE, Y.-H. et al. Effect of oxygen on pitting corrosion of copper pipe in fire sprinkler system. **Materials Chemistry and Physics**, v. 301, p. 127584, jun. 2023.
- LI, S. Y. et al. Application of steel thin film electrical resistance sensor for in situ corrosion monitoring. **Sensors and Actuators, B: Chemical**, v. 120, n. 2, p. 368–377, 2007.
- LIM, K. S. et al. Vibration Mode Analysis for a Suspension Bridge by Using Low-Frequency Cantilever-Based FBG Accelerometer Array. **IEEE Transactions on Instrumentation and Measurement**, v. 70, 2021.
- LIMA, M. R. C. Estudo de técnicas alternativas para o monitoramento ótico de tensões, deformações e temperatura em obras de engenharia. [s.l.] Universidade de Brasília, 2018.

- LIU, H. et al. Detection of early-stage rebar corrosion using a polarimetric ground penetrating radar system. **Construction and Building Materials**, v. 317, 24 jan. 2022a.
- LIU, H. Y. et al. Design of a long-period fiber grating sensor for reinforcing bar corrosion in concrete. **Journal of Intelligent Material Systems and Structures**, v. 23, n. 1, p. 45–51, jan. 2012.
- LIU, P. et al. Investigation of novel embedded piezoelectric ultrasonic transducers on crack and corrosion monitoring of steel bar. **Construction and Building Materials**, v. 235, 28 fev. 2020.
- LIU, Z. et al. Studies on the validity of strain sensors for pavement monitoring: A case study for a fiber Bragg grating sensor and resistive sensor. **Construction and Building Materials**, v. 321, 28 fev. 2022b.
- LU, H.; XI, D.; QIN, G. Environmental risk of oil pipeline accidents. **Science of the Total Environment**, v. 874, 20 maio 2023.
- LV, J. et al. Research on new FBG displacement sensor and its application in Beijing Daxing Airport project. **Optik**, v. 178, n. 122, p. 146–155, 2019.
- LYNCH, S. A review of underlying reasons for intergranular cracking for a variety of failure modes and materials and examples of case histories. Engineering Failure Analysis Elsevier Ltd, , 1 jun. 2019.
- M. EDWARDS. Controlling corrosion in drinking water distribution systems: a grand challenge for the 21st century. **Water Science and Technology**, v. 49, p. 1–8, 2004.
- MA, W. et al. Miniature on-fiber extrinsic Fabry-Perot interferometric vibration sensors based on micro-cantilever beam. **Nanotechnology Reviews**, v. 8, n. 1, p. 293–298, 1 jan. 2019.
- MAALEJ, M. et al. Fiber optic sensing for monitoring corrosion-induced damage. **Structural Health Monitoring**, v. 3, n. 2, p. 165–176, 2004.
- MAJHI, S. et al. Corrosion monitoring in steel bars using Laser ultrasonic guided waves and advanced signal processing. **Mechanical Systems and Signal Processing**, v. 149, 15 fev. 2021.
- MANIE, Y. C. et al. Intensity and wavelength division multiplexing FBG sensor system using a Raman amplifier and extreme learning machine. **Journal of Sensors**, v. 2018, p. 11, 2018.
- MARDANINEJAD, R.; SAFIZADEH, M. S. Gas Pipeline Corrosion Mapping Through Coating Using Pulsed Eddy Current Technique. **Russian Journal of Nondestructive Testing**, v. 55, n. 11, p. 858–867, 1 nov. 2019.

MESQUITA, E. et al. Global overview on advances in structural health monitoring platforms. **Journal of Civil Structural Health Monitoring**, v. 6, n. 3, p. 461–475, 2016a.

MESQUITA, E. et al. Groundwater level monitoring using a plastic optical fiber. **Sensors and Actuators, A: Physical**, v. 240, 2016b.

MESQUITA, E. et al. Optical sensors for bond-slip characterization and monitoring of RC structures. **Sensors and Actuators, A: Physical**, v. 280, 2018.

MEZZADRI, F. Instrumentação óptica de máquinas industriais de grande porte para medição de temperatura. [s.l.] Universidade Tecnológica Federal do Paraná, 2018.

MIN, R. et al. Optical fiber sensing for marine environment and marine structural health monitoring: A review. Optics and Laser Technology Elsevier Ltd., 1 ago. 2021.

MOHD NOOR, N. N.; LEE, M. F. **LPG Mass Monitoring Scale with Automatic Gas Leakage Detector System**. Journal of Physics: Conference Series. **Anais**...Institute of Physics, 2022.

MOUNTASSIR, M. EL et al. An ultrasonic guided waves based prognostic approach for predictive maintenance: Experimental study cases. **Mechanical Systems and Signal Processing**, v. 190, p. 110135, maio 2023.

NASCIMENTO, J. F. et al. Amplified OTDR systems for multipoint corrosion monitoring. **Sensors**, v. 12, n. 3, p. 3438–3448, mar. 2012.

OTIENO, M.; BEUSHAUSEN, H.; ALEXANDER, M. Chloride-induced corrosion of steel in cracked concrete - Part II: Corrosion rate prediction models. **Cement and Concrete Research**, v. 79, p. 386–394, 1 jan. 2016.

PANOSSIAN, Z. Corrosão e proteção em equipamentos e estruturas metálicas. 1. ed. São Paulo: [s.n.]. v. 1

PENG, Z. et al. Distributed fiber sensor and machine learning data analytics for pipeline protection against extrinsic intrusions and intrinsic corrosions. **Optics Express**, v. 28, n. 19, p. 27277, 14 set. 2020.

PEREIRA, L. et al. Interrogation Method with Temperature Compensation Using Ultra-Short Fiber Bragg Gratings in Silica and Polymer Optical Fibers as Edge Filters. **Sensors**, v. 23, n. 1, 1 jan. 2023a.

PEREIRA, L. et al. Bragg Gratings in ZEONEX Microstructured Polymer Optical Fiber With 266 nm Nd:YAG Laser. **IEEE Sensors Journal**, 1 maio 2023b.

PIERACCINI, M. et al. Interferometric radar vs. accelerometer for dynamic monitoring of large structures: An experimental comparison. **NDT and E International**, v. 41, n. 4, p. 258–264, jun. 2008.

POPOV, B. N.; ZHENG, G.; WHITE, R. E. Surface Treatment for Inhibition of Corrosion and Hydrogen Penetration of Type 718 Alloy. **Corrosion**, v. 50, n. 8, p. 613–619, 1994.

QIAO, X. et al. Fiber bragg grating sensors for the oil industry. **Sensors (Switzerland)**, v. 17, n. 3, p. 34, 2017.

QU, H. J. et al. Crystallographic effects on transgranular chloride-induced stress corrosion crack propagation of arc welded austenitic stainless steel. **npj Materials Degradation**, v. 6, n. 1, dez. 2022.

RAHIM, R. A. et al. Ultrasonic Tomography for Monitoring the Corrosion of Steel. **Jurnal Teknologi**, v. 6, p. 151–158, 2015.

RAMÍREZ-CAMACHO, J. G. et al. Assessing the consequences of pipeline accidents to support land-use planning. **Safety Science**, v. 97, p. 34–42, 1 ago. 2017.

RAO, Y.-J. In-fibre Bragg grating sensors. **Measurement Science and Technology**, v. 8, p. 355–375, 1997.

REBELO, C. et al. Cable tensioning control and modal identification of a circular cable-stayed footbridge: Dynamic testing of civil engineering structures series. **Experimental Techniques**, v. 34, n. 4, p. 62–68, 2010.

REN, L. et al. Design and experimental study on FBG hoop-strain sensor in pipeline monitoring. **Optical Fiber Technology**, v. 20, n. 1, p. 15–23, 2014.

REN, L. et al. Pipeline corrosion and leakage monitoring based on the distributed optical fiber sensing technology. **Measurement: Journal of the International Measurement Confederation**, v. 122, p. 57–65, 1 jul. 2018.

RODRIGUES, C. et al. Development of a long-term monitoring system based on FBG sensors applied to concrete bridges. **Engineering Structures**, v. 32, n. 8, p. 1993–2002, 2010.

RODRIGUES, C. et al. FBG based strain monitoring in the rehabilitation of a centenary metallic bridge. **Engineering Structures**, v. 44, p. 281–290, 2012.

SAHU, S.; FRANKEL, G. S. Effect of substrate orientation and anisotropic strength on corrosion pits. **Corrosion Science**, v. 211, 1 fev. 2023.

SENIOR, N. A. et al. The measurement of ultra low uniform corrosion rates. **Corrosion Science**, v. 176, 1 nov. 2020.

- SHEN, N.; CHEN, L.; CHEN, R. Multi-route fusion method of GNSS and accelerometer for structural health monitoring. **Journal of Industrial Information Integration**, v. 32, 1 abr. 2023.
- SHOKRI, N. H.; AMIN, Z. M.; SELI, V. A. **Non-Destruction Method for Detecting Corroded Underground Pipe Using Ground Penetrating Radar**. IOP Conference Series: Earth and Environmental Science. **Anais**...Institute of Physics Publishing, 4 ago. 2020.
- SILVA, G. E.; Implementação e caracterização da resposta dinâmica de transdutores de deformação e temperatura a fibras ópticas baseados em redes de bragg. [s.l.] Universidade de São Paulo, 2011.
- SILVA, L. C. B.; SEGATTO, M. E. V.; CASTELLANI, C. E. S. Raman scattering-based distributed temperature sensors: A comprehensive literature review over the past 37 years and towards new avenues. **Optical Fiber Technology**, v. 74, 1 dez. 2022.
- SIWOWSKI, T. et al. Distributed fibre optic sensors in FRP composite bridge monitoring: Validation through proof load tests. **Engineering Structures**, v. 246, n. January, p. 13, 2021.
- SOHN, H. et al. A Review of Structural Health Monitoring Literature 1996 2001. [s.l: s.n.].
- SOUSA, I. et al. Sensing System Based on FBG for Corrosion Monitoring in Metallic Structures. **Sensors**, v. 22, n. 16, 1 ago. 2022.
- SOUZA, S. A. DE. Ensaios mecânicos de materiais metálicos Fundamentos teóricos e práticos. [s.l: s.n.]. v. 5
- STEWART, M. G.; ASCE, M.; VAL, D. V. Multiple Limit States and Expected Failure Costs for Deteriorating Reinforced Concrete Bridges. **J. Bridge Eng.**, v. 8, p. 405–415, 2003.
- SUN, L. et al. Early Monitoring of Rebar Corrosion Evolution Based on FBG Sensor. **International Journal of Structural Stability and Dynamics**, v. 18, n. 8, 1 ago. 2018.
- SUN, L.; CHEN, C.; SUN, Q. Q. Experimental and finite element analyses on the corrosion of underground pipelines. **Science China Technological Sciences**, v. 58, n. 6, p. 1015–1020, 10 jun. 2015.
- SUN, M. et al. Pipeline leakage monitoring experiments based on evaporation-enhanced FBG temperature sensing technology. **Structural Control and Health Monitoring**, v. 28, n. 3, 1 mar. 2021.
- SUN, X. et al. A novel method for steel bar all-stage pitting corrosion monitoring using the feature-level fusion of ultrasonic direct waves and coda waves. **Structural Health Monitoring**, v. 22, n. 1, p. 714–729, 1 jan. 2023.

TAHERI, H.; JONES, C.; TAHERI, M. Assessment and detection of stress corrosion cracking by advanced eddy current array nondestructive testing and material characterization. **Journal of Natural Gas Science and Engineering**, v. 102, 1 jun. 2022.

TANG, F. et al. A review on fiber optic sensors for rebar corrosion monitoring in RC structures. **Construction and Building Materials**, Elsevier Ltd, , 27 dez. 2021a.

TANG, J. et al. In-situ monitoring and analysis of the pitting corrosion of carbon steel by acoustic emission. **Applied Sciences (Switzerland)**, v. 9, n. 4, 18 fev. 2019.

TANG, Z. et al. Cause analysis and preventive measures of pipeline corrosion and leakage accident in alkylation unit. **Engineering Failure Analysis**, v. 128, 1 out. 2021b.

TEIXEIRA, A. P. et al. Reliability of pipelines with corrosion defects. **International Journal of Pressure Vessels and Piping**, v. 85, n. 4, p. 228–237, abr. 2008.

THIBBOTUWA, U. C.; CORTÉS, A.; IRIZAR, A. Ultrasound-Based Smart Corrosion Monitoring System for Offshore Wind Turbines. **Applied Sciences (Switzerland)**, v. 12, n. 2, 1 jan. 2022.

**Thorlabs, Ultra-High NA Waveguide Splice Fiber**. Disponível em: <a href="https://www.thorlabs.com/newgrouppage9.cfm?objectgroup\_id=340">https://www.thorlabs.com/newgrouppage9.cfm?objectgroup\_id=340</a>. Acesso em: 25 abr. 2023.

TU, G. et al. Strain variation measurement with short-time Fourier transform-based Brillouin optical time-domain reflectometry sensing system. **Electronics Letters**, v. 50, n. 22, p. 1624–1626, 23 out. 2014.

VAHDATI, N. et al. External corrosion detection of oil pipelines using fiber optics. **Sensors (Switzerland)**, v. 20, n. 3, p. 1–16, 2020.

VAN DER KOOI, K.; HOULT, N. A. Assessment of a steel model truss using distributed fibre optic strain sensing. **Engineering Structures**, v. 171, n. October 2017, p. 557–568, 2018.

WAN, K. T.; LEUNG, C. K. Y.; CHEN, L. A novel optical fiber sensor for steel corrosion in concrete structures. **Sensors**, v. 8, n. 3, p. 1960–1976, 2008.

WANG, D. et al. A double-mass block acceleration sensor based on FBG. **Optical Fiber Technology**, v. 66, 1 out. 2021.

WANG, J. et al. Pipeline leak detection and corrosion monitoring based on a novel FBG pipe-fixture sensor. **Structural Health Monitoring**, v. 21, n. 4, p. 1819–1832, 1 jul. 2022a.

WANG, X. et al. Corrosion process of Mg–Sn alloys revealed via in situ synchrotron X-ray radiography. **Materials Letters**, v. 308, 1 fev. 2022b.

- WASIF, R. et al. Development of Permanently Installed Magnetic Eddy Current Sensor for Corrosion Monitoring of Ferromagnetic Pipelines. **Applied Sciences (Switzerland)**, v. 12, n. 3, 1 fev. 2022.
- WU, J. et al. Multi-agent system design and evaluation for collaborative wireless sensor network in large structure health monitoring. Expert Systems with Applications, 2010.
- WU, R. et al. Nondestructive Testing for Corrosion Evaluation of Metal under Coating. Journal of SensorsHindawi Limited, , 2021.
- YAACOUBI, S. et al. Measurement investigations in tubular structures health monitoring via ultrasonic guided waves: A case of study. **Measurement: Journal of the International Measurement Confederation**, v. 147, 1 dez. 2019.
- YAN, G. et al. A novel strain-decoupled sensitized FBG temperature sensor and its applications to aircraft thermal management. **Optics and Laser Technology**, v. 140, 1 ago. 2021.
- YANG, X. et al. Groundwater geochemical constituents controlling the reductive dechlorination of TCE by nZVI: Evidence from diverse anaerobic corrosion mechanisms of nZVI. **Chemosphere**, v. 262, 1 jan. 2021.
- YE, C. et al. Evaluating in-service structural behaviour of an operational railway bridge using fibre optic sensing and structural model updating. **Engineering Structures**, v. 247, n. September, p. 113116, 2021.
- YE, X. W.; NI, Y. Q.; YIN, J. H. Safety Monitoring of Railway Tunnel Construction Using FBG Sensing Technology. **Advances in Structural Engineering**, v. 16, n. 8, p. 1401–1409, 2013.
- YE, X. W.; SU, Y. H.; XI, P. SEN. Statistical analysis of stress signals from bridge monitoring by FBG system. **Sensors (Switzerland)**, v. 18, n. 2, 2018.
- YU, S. et al. Laboratory validation of in-pipe pulsed thermography in the rapid assessment of external pipe wall thinning in buried metallic utilities. **NDT and E International**, v. 135, 1 abr. 2023.
- ZHANG, D. et al. Internal deformation monitoring for centrifuge slope model with embedded FBG arrays. **Landslides**, v. 14, n. 1, p. 407–417, 2017.
- ZHANG, H. et al. A low noise capacitive MEMS accelerometer with anti-spring structure. **Sensors and Actuators, A: Physical**, v. 296, p. 79–86, 1 set. 2019.
- ZHANG, X. et al. The pitting to uniform corrosion evolution process promoted by large inclusions in mooring chain steels. **Materials Characterization**, v. 181, 1 nov. 2021.

ZHAO, X. et al. Brillouin corrosion expansion sensors for steel reinforced concrete structures using a fiber optic coil winding method. **Sensors**, v. 11, n. 11, p. 10798–10819, nov. 2011.

ZHAO, X. et al. A Fiber Bragg Grating acceleration sensor with temperature compensation. **Optik**, v. 241, 1 set. 2021.

ZOU, F.; CEGLA, F. B. On quantitative corrosion rate monitoring with ultrasound. **Journal of Electroanalytical Chemistry**, v. 812, p. 115–121, 1 mar. 2018.

## SCIENTIFIC PUBLICATIONS RESULTED FROM THE WORK DEVELOPED

#### **Article in international Journal**

## **Published:**

- Sousa, Israel.; Pereira, Luis.; Mesquita, Esequiel.; Souza, Vitória L.; Araújo, Walney S.; Cabral, Antônio.; Alberto, Nélia.; Varum, Humberto.; Antunes, Paulo. Sensing System Based on FBG for Corrosion Monitoring in Metallic Structures. Sensors 2022, 22, 5947. https://doi.org/10.3390/s22165947
- Diaz, Camilo, **Sousa, Israel**, Mesquita, Esequiel et al. Low-cost optical interrogator system for structural health monitoring. J. Build. Rehabil. **8**, 54 (2023). https://doi.org/10.1007/s41024-023-00313-2

## **Submitted:**

 Luis Pereira, Israel Sousa, Esequiel Mesquita, Antônio Cabral, Nélia Alberto, Camilo Diaz, Humberto Varum and Paulo Antunes. FBG-based accelerometer for buried pipeline natural Frequency monitoring and corrosion detection. Submitted to Measurement Journal

## **Article in conference proceedings**

Pereira, Luís; Sousa, Israel; Mesquita, Esequiel; Souza, Vitória; Araújo, Walney S.; Alberto, Nélia; Varum, Humberto; Antunes, Paulo. "Deteção da fase inicial da corrosão numa placa metálica usando redes de Bragg em fibra ótica." In: 6ª Jornada Portuguesa de Engenharia de Estruturas. Lisboa, 2022.